

# pH buffer solutions

## ■ For calibration of pH sensors



## description

The slope of pH sensors changes over the time (depending on the measuring media). We recommend a regular calibration with our buffer solutions. We offer 1000 ml packages of pH 2, pH 3,56, pH 4, pH 7, and pH 9,22, and 50 ml packages of pH 4, and pH 7.

## order information

<u>name</u>	<u>description</u>	<u>article number</u>
pH 2 - cal	1000 ml buffer solution pH 2	95212000K
pH 3,56 - cal	1000 ml buffer solution pH 3,56	95212003K
pH 4 - cal	1000 ml buffer solution pH 4	95212007K
pH 4 - cal	50 ml buffer solution pH 4	95212010K
pH 7 - cal	1000 ml buffer solution pH 7	95212001K
pH 7 - cal	50 ml buffer solution pH 7	95212009K
pH 9,22 - cal	1000 ml buffer solution pH 9,22	95212004K

